

# WASTEWATER STEWARDSHIP REPORT

DATE	TIME (24H clock)	DURA- TION	LOCATION	LOCATION DESCRIPTOR	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m <sup>3</sup> )	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
14-Nov-16	16:00	48 hrs	OTHER	544 Spruce St, Sudbury	Other	Receiving Water	Nolin Creek	n/a	none	OTHER	cross connection	MODERATE sewer overflow; limited amount entering receiving stream