

**PLANT BYPASS / OVERFLOW LOG**

REVISED: 9-Mar-20

#	DATE	TIME (24H clock)	DURATION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	Pit / LS / Other	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m <sup>3</sup> )	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
2	23-Feb-20	15:30	34 hrs	Coniston WWTP	121 Gov't Rd	plt	Plant bypass: flow exceeds design capacity	Receptor not impa	Coniton Creek	300.0	meas	Full Treatment	Maintenance	Maintenance	disinfection procedures followed;