



PLANT BYPASS/OVERFLOW LOG

2nd Quarter 2020

REVISED: 8-May-20

#	DATE	TIME (24H clock)	DURATION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	Pit / LS / Other	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m ³)	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMPLIANCE TEST RESULTS OK?	COMMENTS / RELEVANCE
15	01-May-20	0:10	5.5 hrs	Sudbury WWTP	1271 Kelly Lake Road	plt	Plant bypass	Receiving water	Junction Creek	2,083.0	meas	screening and c12 5	Heavy rain	spring runoff		disinfection procedures followed;
21	01-May-20	9:45	45 hrs	Coniston WWTP	121 Government Rd.	plt	Plant bypass: flow exceeds design capacity	Receiving water	Coniton Creek	2,880.0	meas	Full Treatment	Heavy rain	spring runoff		disinfection procedures followed;