	PLANT BYPASS / OVERFLOW LOG REVISED									REVISED:	15-Oct-19					
	# 1	DATE	TIME (24H clock)	DURATION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	Plt / LS / Other	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m³)	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
5	8 03	S-Sep-19	21:06	3.0 hrs	Coniston WWTP	Coniston	Plt	Plant bypass: flow exceeds design capacity	Receiving water	Coniston Creek	625.0	Meas	4.0 kg of Cl2	Heavy rain	Heavy Rain	MINOR release of wastewater; disinfection procedures followed; no release to environment
5	9 17	'-Sep-19	7:00	0.25 hrs	Sudbury WWTP	Sudbury	Plt	Collection system overflow	Receptor not impa	n/a	1.0	Est	1.0 kg of HTH	Equipment (failure)		MINOR release of wastewater; disinfection procedures followed; no release to