

# WASTEWATER STEWARDSHIP REPORT

DATE	TIME <small>(24H clock)</small>	DURA- TION	LOCATION	LOCATION DESCRIPTOR	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m <sup>3</sup> )	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
12-Oct-16	12:00	1.0 hr	Manhole (#)	52 Elm Street, Sudbury	OTHER	Receptor not impacted	Junction Creek	0.0	none	Sanitary sewer overflow	Sewer blockage	MINOR sewer overflow; contained at immediate site; nothing entered receiving stream