WASTEWATER STEWARDSHIP REPORT

	DATE	TIME (24H clock)	DURA- TION	LOCATION	LOCATION DESCRIPTOR	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m³)	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
3	0-Aug-16	00-Jan-00	3.0 hrs	Walden WWTP		Plant bypass: flow exceeds design capacity	Receiving water	Simon Creek	981	0.9 kgs of Cl2	Heavy rain	Heavy Flows	MODERATE sewer overflow; limited amount entering receiving stream
3	0-Aug-16	00-Jan-00	13.0 hrs	Lively WWTP		Plant bypass: flow exceeds design capacity	Receiving water	Meatbird Creek	832	0.7 kgs of Cl2	Heavy rain	Heavy Flows	MODERATE sewer overflow; limited amount entering receiving stream