WASTEWATER STEWARDSHIP REPORT

DATE	TIME (24H clock)	DURA- TION	LOCATION	LOCATION DESCRIPTOR	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m³)	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
05-Feb-16	13:45	0.1 hrs	Walden WWTP	Lively	OTHER	Receptor not impacted	Simon Creek	2.0	2 kg of HTH	Equipment (failure)	discharge pipe disabled	MINOR release of wastewater contained on site; disinfection procedures followed