

STEWARDSHIP REPORT

August 2017

PLANT BYPASS / OVERFLOW LOG

DATE	TIME (24H clock)	DURA- TION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	TYPE OF OCCURRENCE	RECEIVING STREAM ID	VOL (m ³)	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
02-Aug-17	14:00	1.5 hrs	OTHER	2050 Regent St	Collection system overflow	Receptor not impacted	0.1	est	0.5 kg of HTH	Sanitary sewer overflow	sewer blockage	MINOR release of wastewater; disinfection procedures followed; contained on site
11-Aug-17	15:15	7.25 hrs	Walden WWTP	Walden	Plant bypass: flow exceeds design capacity	Receiving water	353.0	meas	1.0 kg of Cl2	Maintenance	Heavy Rain - long duration	MINOR release of wastewater; disinfection procedures followed; no release to environment
11-Aug-17	15:53	69.25 hrs	Coniston WWTP	Coniston	Plant bypass: flow exceeds design capacity	Receiving water	1,391.0	meas	1.0 kg of Cl2	Maintenance	Heavy Rain - long duration	MINOR release of wastewater; disinfection procedures followed; no release to environment
18-Aug-17	18:10	1.5 hrs	OTHER	1500 Regent St	Collection system overflow	Receiving water	0.1	est	6.0 litres of Javel12	Sanitary sewer overflow	sewer blockage	MINOR release of wastewater; disinfection procedures followed
18-Aug-17	0:00	12.5 hrs	Walden WWTP	Walden	Plant bypass: flow exceeds design capacity	Receptor not impacted	1,524.0	meas	1.5 kg of Cl2	Maintenance	Heavy Rain - long duration	MINOR release of wastewater; disinfection procedures followed; no release to environment
18-Aug-17	0:15	24 hrs	Coniston WWTP	Coniston	Plant bypass: flow exceeds design capacity	Receiving water	1,536.0	meas	2.0 kg of Cl2	Heavy rain	Heavy Rain - long duration	MINOR release of wastewater; disinfection procedures followed; no release to environment
18-Aug-17	2:00	1.75 hrs	Walden WWTP	Walden	Plant bypass	Receiving water	2.0	meas	0.1 kg of Cl2	Maintenance	Heavy Rain - long duration	MINOR release of wastewater; disinfection procedures followed
23-Aug-17	1:05	10.9 hrs	Lively WWTP	Lively	Plant bypass: flow exceeds design capacity	Receiving water	208.0	meas	0.2 kg of Cl2	Heavy rain	Heavy Rain - long duration	MINOR release of wastewater; disinfection procedures followed; no release to environment
18-Aug-17	6:30	43 hrs	Azilda WWTP	Azilda	Plant bypass	Receiving water	1,571.0	meas	13 kg of Cl2	Maintenance	Heavy Rain - long duration	MINOR release of wastewater; disinfection procedures followed
22-Aug-17	10:30	66 hrs	Azilda WWTP	Azilda	Plant bypass	Receiving water	1,843.0	meas	18 kg of Cl2	Maintenance	Heavy Rain - long duration	MINOR release of wastewater; disinfection procedures followed