

WASTEWATER STEWARDSHIP REPORT

DATE	TIME <small>(24H clock)</small>	DURA- TION	LOCATION	LOCATION DESCRIPTOR	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m ³)	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
24-Jan-16	07:04 hrs	1.75 hrs	Azilda WWTP	Azilda	Plant bypass	Receiving water	Pilon Creek	68.1	1 kg of Cl2	Equipment (failure)	raw valve obstructed	MODERATE sewer overflow; contained at immediate site; limited amount entering receiving stream
24-Jan-16	13:58	2.75 hrs	Valley East WWTP	Val Therese	OTHER	Receptor not impacted	Whitson River	5.0	1.0 kg of Cl2	Equipment (failure)	Small hole developed in Sludge Tank	MINOR release of wastewater contained on site; disinfection procedures followed