STEWARDSHIP REPORT

PLANT BYPASS / OVERFLOW LOG												
DATE	TIME (24H clock)	DURA- TION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	TYPE OF OCCURRENCE	RECEIVING STREAM ID	VOL (m³)	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
13-Jul-17	7:30	5 hrs	Walden WWTP	lWalden	Plant bypass: flow exceeds design capacity	Simon Creek	2,500.0	meas	15 kg of Cl2	Maintenance	Construction of Clarifier - contained on site	MINOR release of wastewater; disinfection procedures followed
24-Jul-17	3:00	16 hrs	Coniston WWTP	Coniston	Plant bypass: flow exceeds design capacity	Coniston Creek	1,024.0	meas	5.5 kg of Cl2	Heavy rain	Heavy Rain - long duration	MINOR release of wastewater; disinfection procedures followed