



PLANT BYPASS / OVERFLOW LOG

1st Quarter 2019

REVISED: 29-Jan-20

#	DATE	TIME (24H clock)	DURATION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	Plt / LS / Other	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m ³)	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
1	18-Jan-20	11:00	3.5 hrs	Lively WWTP	44 Niemi Rd, Lively	Plt	Collection system overflow	Receptor not impacted	n/a	0.2	Est	1kg of HTH Shock-it	OTHER	Sewermain Blockage	MINOR release of wastewater; disinfection procedures followed; no release to environment