



**2nd Quarter  
2022**

REVISED: 20-Jun-22

**PLANT BYPASS / OVERFLOW LOG**

#	DATE	TIME (24H clock)	DURATION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	Plt / LS / Other	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m <sup>3</sup> )	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES
32	May 27-22	24:00 hrs	24 hrs	Valley East WWTP	1317 Yorkshire Dr.	PLT	Plant bypass: flow exceeds design capacity	Receiving water	Vermillion River	87 m3	flow meter	full treatment	Planned maintenance downtime	rain
33	May 30 - 22	11:30	10 min	Coniston WWTP	121 Gov't rd	PLT	Plant overflow	Receptor not impacted	NA	0.3	est	Disinfection/dilution/removal	Equipment (failure)	