



**PLANT BYPASS / OVL... LOW LOG**

**2nd Quarter 2020**

REVISED: **10-Aug-20**

#	DATE	TIME (24H clock)	DURATION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	Pit / LS / Other	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m <sup>3</sup> )	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMPLIANCE TEST RESULTS OK?	COMMENTS / RELEVANCE
24	02-Jun-20	12:57	16 days	Coniston WWTP	121 Government Rd.	pit	Plant bypass: flow exceeds design capacity	Receiving water	Coniton Creek	3,143.00	meas	Full Treatment		Maintenance		disinfection procedures followed;
25	24-Jun-20	10:00	7 days	Coniston WWTP	121 Government Rd.	pit	Plant bypass: flow exceeds design capacity	Receiving water	Coniton Creek	530.00	meas	Full Treatment	Planned maintenance downtime			disinfection procedures followed;