



**PLANT BYPASS / OVERFLOW LOG**

**3rd Quarter 2020**

REVISED: 10-Aug-20

#	DATE	TIME <small>(24H clock)</small>	DURATION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	Pit / LS / Other	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m <sup>3</sup> )	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
26	08-Jul-20	18:30	4hrs	Vermilion River LS	99 Lakeshore St	LS	Collection system overflow	Receiving water	Vermillion River	250.00	Est	none	Heavy rain		
27	07-Jul-20	10:30	00-Jan-00	Moonlight Ave LS	358 Moonlight	LS	Collection system overflow	Receiving water	Rumford Crk	1.00	Est	none	Equipment (failure)		
28	19-Jul-20	16:00	20 min.	Sudbury WWTP	1275 Kelly Lake Rd	Pit	Plant bypass: flow exceeds design capacity	none	none	0.05	Est	Full Treatment	Maintenance		sludge foam overflow - disinfection procedures followed;