



3rd Quarter  
2021

REVISED: 13-Oct-21

PLANT BYPASS / OVERFLOW LOG

#	DATE	TIME (24H clock)	DURATION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	Pit / LS / Other	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m <sup>3</sup> )	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
16	03-Aug-21	16:40	4hrs 30min	Chelmsford WWTP	265 Laurette	Plant	Plant bypass	None	Whitson River	1,486.0	SCADA	Partial Treatment	Equipment (failure)	None	
17	10-Aug-21	3:19	2 hrs 35 min	Lively WWTP	231 First Ave	Plant	Plant bypass: flow exceeds design capacity	None	Meatbird Creek	696.0	Flow meter	Full Treatment	Heavy rain	None	