

PLANT BYPASS / OVERFLOW LOG

REVISED: **3-Sep-18**

#	DATE	TIME (24H clock)	DURATION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	Plt / LS / Other	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m ³)	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
24	29-Aug-18	3:00	8.5 hrs	Coniston WWTP	Coniston	Plt	Plant bypass	Receiving water	Coniston Creek	480.0	Meas	4.5 kgs of Cl2	Heavy rain	flash rain storm	Moderate release precipitated by warming and rain; flow fully treated.