

PLANT BYPASS / OVERFLOW LOG

REVISED: 15-Oct-19

#	DATE	TIME (24H clock)	DURATION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	Plt / LS / Other	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m ³)	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
56	11-Jul-19	12:15	4.5 hrs	Coniston WWTP	Coniston	Plt	Plant bypass: flow exceeds design capacity	Receiving water	Coniston Creek	260.0	Meas	1.8 kg of Cl2	Equipment (failure)	Heavy rain	MINOR release of wastewater; disinfection procedures followed; no release to environment
57	24-Jul-19	0:00	168.0 hrs	Valley East WWTP	Val Caron	Plt	Plant bypass: flow exceeds design capacity	Receiving water	Vermillion River	3,024.0	Est	1.5 kg of Cl2	Maintenance	Heavy rain	MINOR release of wastewater; disinfection procedures followed; no release to environment