

PLANT BYPASS / OVERFLOW LOG

REVISED: 3-Dec-18

#	DATE	TIME (24H clock)	DURATION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	Plt / LS / Other	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m ³)	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
44	06-Nov-18	17:30	8.0 hrs	Coniston WWTP	Coniston	Plt	Plant bypass: flow exceeds design capacity	Receiving water	Coniston Creek	512.0	Meas	4.0 kg of Cl2	OTHER	Heavy Rain	MINOR release of wastewater;
45	07-Nov-18	0:00	24 hrs	Valley East WWTP	Val Therese	Plt	Plant bypass: flow exceeds design capacity	Receiving water	Whitson River	2,036.0	Est	54.5 kg of Cl2	OTHER	Heavy Rain	MINOR release of wastewater;
46	19-Nov-18	0:00	48 hrs	Valley East WWTP	Val Therese	Plt	Plant bypass: flow exceeds design capacity	Receiving water	Whitson River	355.0	Est	18 kg of Cl2	OTHER	Snow Melt	MINOR release of wastewater;
47	14-Nov-18	15:30	360 hrs	Coniston WWTP	Coniston	Plt	Plant bypass: flow exceeds design capacity	Receiving water	Coniston Creek	191.0	Meas	55 kg of Cl2	Maintenance	n/a	MINOR release of wastewater;