

PLANT BYPASS / OVERFLOW LOG

REVISED:

#	DATE	TIME (24hr clock)	DURATION	LOCATION	LOCATION DESCRIPTOR / ADDRESS	Pit / LS / Other	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m ³)	Est or Meas?	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
54	15-Nov-17	23:56	15.5 hrs	Chelmsford WWTP	Laurette St., Chelmsford	Pit	Plant bypass: flow exceeds design capacity	Receptor not impacted	Whitson Creek	1,780.0	meas	n/a	Maintenance	n/a	MINOR release of wastewater; disinfection procedures followed; no release to environment
55	17-Nov-17	9:00	1.5 hrs	OTHER	2008 Bancroft Dr	Other	Collection system overflow	Receptor not impacted		1.0	est	n/a	Maintenance	n/a	MINOR release of wastewater; disinfection procedures followed; no release to environment