WASTEWATER STEWARDSHIP REPORT

DATE	TIME (24H clock)	DURA- TION	LOCATION	LOCATION DESCRIPTOR	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m³)	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
29-Mar-16	12:30	840 hrs	Wahnapitae Lagoon	Wahnapitae Cell #3	Plant bypass	Receiving water	Wanapitei River	3,000.0	n/a	Spring run-off	Cell #3 leaking	MODERATE sewer overflow; limited amount entering receiving stream
21-Apr-16	16:30	1.6 hrs	OTHER	Martindale Rd @ Copper St	Collection system overflow	Receiving water	Junction Creek	2.0	n/a	Sanitary sewer overflow	Heavy Flows	Moderate release; limited amount entered receiving stream.
15-Apr-16	12:00	226 hrs	Coniston WWTP	Coniston	Plant bypass: flow exceeds design capacity	Receptor not impacted	Coniston Creek	4,601.0	65.9 kg of Cl2	Spring run-off	Heavy Flows	Moderate release; limited amount entered receiving stream.
16-Apr-16	0:01	264 hrs	Valley East WWTP	Val Caron	Plant bypass: flow exceeds design capacity	Receptor not impacted	Whitson River	49,992.0	61.4 kg of Cl2	Spring run-off	Heavy Flows	MINOR sewer overflow; contained at immediate site; nothing entered receiving stream
05-Apr-16	10:10	480.0 hrs	Wahnapitae Lagoon	Wahnapitae Cell #2	Plant bypass	Receiving water	Wanapitei River	3,000.0	n/a	Spring run-off	Cell #2 leaking	MINOR sewer overflow; contained at immediate site; nothing entered receiving stream
09-May-16	13:30	1.0 hr	OTHER	1394 Kingsway, Sudbury	Collection system overflow	Receptor not impacted	n/a	0.0	n/a	Sanitary sewer overflow	Blockage in Manhole	MINOR sewer overflow; contained at immediate site; nothing entered receiving stream
16-May-16	6:35	10.75 hrs	Coniston WWTP	Coniston	Plant bypass: flow exceeds design capacity	Receiving water	Coniston Creek	48.0	2.3 kg of CI2	Heavy rain	Heavy Flows	Minor release; limited amount entered receiving stream.