

WASTEWATER STEWARDSHIP REPORT - 2015 1st QUARTER

REVISED: 3-Mar-15

DATE	TIME (24H clock)	DURA- TION	LOCATION	LOCATION DESCRIPTOR	TYPE OF OCCURRENCE	SENSITIVE RECEPTOR	RECEIVING STREAM ID	VOL (m ³)	LEVEL OF TREATMENT RECEIVED	REASON FOR EVENT	OUTSIDE INFLUENCES	COMMENTS / RELEVANCE
06-Feb-15	14:00	4.0 hrs	Wahnapiatae Lagoon	Wahnapiatae	Plant bypass	Receptor not impacted	Wanup River	1.0	Not Applicable	Equipment (failure)	None	MINOR release of wastewater contained on site
08-Feb-15	18:30	0.5 hrs	Valley East WWTP	Val Therese	Spill (environmental)	Receptor not impacted	Whitson River	0.5	0.5 kg of HTH	Equipment (failure)	None	MINOR release of wastewater contained on site; disinfection procedures followed
25-Feb-15	15:20	2.75 hrs	Azilda WWTP	Azilda	Plant bypass	Receptor not impacted	Whitson River	106.0	2 kg of Cl2	Maintenance	None	MINOR release of wastewater contained on site; disinfection procedures followed